

Bangladesh - Summary of WASH Assessment in UNHCR Supported Camps 2018

Office of the High Commissioner for Refugees, United Nations Refugee Agency

Report generated on: April 7, 2021

Visit our data catalog at: <https://microdata.worldbank.org/index.php>

Overview

Identification

ID NUMBER
BGD_2018_SWEEP_v01_M

Version

VERSION DESCRIPTION
Version 2.1: Edited, anonymous dataset for licensed distribution.

PRODUCTION DATE
2020-02-20

Overview

ABSTRACT
From 2 October to 18 November 2018, UNHCR carried out a Water, Sanitation and Hygiene (WASH) sweep assessment on water points, latrines and bathing facilities in 14 refugee camps. These include Kutupalong and Nayapara registered camps, and the Transit Centre. The assessment cover basic information on location, status, quality, the privacy of facilities and issues such as the management of menstrual hygiene and facilities for persons with specific needs.

The dataset contains 3 modules: bathing (12,259 observations), latrine (11,490 observations) and water points (6,767 observations).

UNITS OF ANALYSIS
Shelter

Scope

NOTES
The scope of the study includes:

- Conditions of facilities (status, quality)
- Location of facilities
- Privacy of facilities
- General issues (management of menstrual hygiene, facilities for persons with specific needs)

TOPICS

| Topic | Vocabulary | URI |
|------------------------------|------------|-----|
| Shelter/Other Infrastructure | | |

Coverage

GEOGRAPHIC COVERAGE
14 refugee camps in Bangladesh, including Kutupalong and Nayapara registered camps, and the Transit Centre.

Producers and Sponsors

PRIMARY INVESTIGATOR(S)

| Name | Affiliation |
|--|-------------|
| Office of the High Commissioner for Refugees | OHCHR |
| United Nations Refugee Agency | UNHCR |

Metadata Production

METADATA PRODUCED BY

| Name | Abbreviation | Affiliation | Role |
|--|--------------|-------------------------------|----------------------------|
| Office of the High Commissioner for Refugees | OHCHR | United Nations Refugee Agency | Documentation of the study |

DATE OF METADATA PRODUCTION

2021-03-31

DDI DOCUMENT VERSION

Version 1 (March 2021). This version is identical to UNHCR DDI ID: Bangladesh_SWEEP_2018_Study_Documentation, except the following edits were made:

- Minor spelling and grammatical corrections
- Specified the archive where study is originally stored

DDI DOCUMENT ID

DDI_BGD_2018_SWEEP_v01_M

Sampling

Sampling Procedure

N/A

Weighting

No weights are provided

Questionnaires

No content available

Data Collection

Data Collection Dates

| Start | End | Cycle |
|--------------|------------|--------------|
| 2018-10-02 | 2018-11-18 | N/A |

Data Collection Mode

Other [oth]

Data Collectors

| Name | Abbreviation | Affiliation |
|--|---------------------|-------------------------------|
| Office of the High Commissioner for Refugees | OHCHR | United Nations Refugee Agency |

Data Processing

Data Editing

Dataset was edited and anonymised with local suppression and variable removal.

Data Appraisal

No content available

File Description

Variable List

BGD_WASH_SWEEP_2018_Bathing

| | |
|--------------|--|
| Content | This file contains all bath related data collected during this assessment. |
| Cases | 0 |
| Variable(s) | 21 |
| Structure | Type: Keys: () |
| Version | |
| Producer | |
| Missing Data | |

Variables

| ID | NAME | LABEL | TYPE | FORMAT | QUESTION |
|-----|------------------------|---|----------|-----------|----------|
| V1 | id | ID | contin | numeric | |
| V2 | camp | Camp Name | discrete | character | |
| V3 | facility_gender | Gender that uses the facility | discrete | character | |
| V4 | number_doors | Number of doors | discrete | numeric | |
| V5 | construction_status | Construction Status | discrete | character | |
| V6 | functional_chamber | Number of functional chambers | discrete | numeric | |
| V7 | non_functional_chamber | Number of non functional chambers | discrete | numeric | |
| V8 | repair_need | Is repair needed? | discrete | character | |
| V9 | why_non_functional | Why is the bathing facility non functional? | discrete | character | |
| V10 | structure | Structure type | discrete | character | |
| V11 | door_close | Does the door close properly? | discrete | character | |
| V12 | see_through | Can you see through? | discrete | character | |
| V13 | inside_door_close | Can you close the door from the inside? | discrete | character | |
| V14 | outside_door_close | can you close the door from the outside? | discrete | character | |
| V15 | mhm_raised_plateform | For menstrual hygiene management, is a raised platform available? | discrete | numeric | |
| V16 | mhm_hanger | For menstrual hygiene management, is a hanger for drying clothes available? | discrete | numeric | |
| V17 | mhm_none | For menstrual hygiene management, is none available? | discrete | numeric | |
| V18 | available_drain | Is there a drain available? | discrete | character | |
| V19 | drain_type | Type of drain | discrete | character | |
| V20 | install_year | Year of installation | discrete | numeric | |
| V21 | install_month | Month of installation | discrete | numeric | |

BGD_WASH_SWEEP_2018_Latrine

| | |
|--------------|---|
| Content | This file contains all latrine related data collected during this assessment. |
| Cases | 0 |
| Variable(s) | 28 |
| Structure | Type: Keys: () |
| Version | |
| Producer | |
| Missing Data | |

Variables

| ID | NAME | LABEL | TYPE | FORMAT | QUESTION |
|-----|------------------------|---|----------|-----------|----------|
| V22 | id | Facility ID | contin | numeric | |
| V23 | camp | Camp Name | discrete | character | |
| V24 | facility_gender | Gender that uses the facility | discrete | character | |
| V25 | latrine_type | | discrete | character | |
| V26 | number_doors | Number of doors | discrete | numeric | |
| V27 | construction_status | Construction Status | discrete | character | |
| V28 | functional_chamber | Number of functional chambers | discrete | numeric | |
| V29 | repair_need | Is repair needed? | discrete | character | |
| V30 | non_functional_chamber | Number of non functional chambers | discrete | numeric | |
| V31 | why_non_functional | Why is the bathing facility non functional? | discrete | character | |
| V32 | handwash_device | | discrete | character | |
| V33 | handwash_device_ok | | discrete | character | |
| V34 | handwash_device_water | | discrete | character | |
| V35 | soap | | discrete | character | |
| V36 | light | | discrete | character | |
| V37 | structure | Structure type | discrete | character | |
| V38 | door_close | Does the door close properly? | discrete | character | |
| V39 | see_through | Can you see through? | discrete | character | |
| V40 | inside_door_close | Can you close the door from the inside? | discrete | character | |
| V41 | outside_door_close | can you close the door from the outside? | discrete | character | |
| V42 | pwsn_hand_rail_outside | Is a rail (outside) available for pwsn? | discrete | numeric | |
| V43 | pwsn_hand_rail_inside | Is a rail (inside) available for pwsn? | discrete | numeric | |
| V44 | pwsn_ramp | Is a ramp available for pwsn? | discrete | numeric | |
| V45 | pwsn_high_commode | Is a high commode available for pwsn? | discrete | numeric | |
| V46 | pwsn_stairs | Are stairs available for pwsn? | discrete | numeric | |
| V47 | pwsn_none | Is none available for pwsn? | discrete | numeric | |
| V48 | install_year | Year of installation | contin | numeric | |
| V49 | install_month | Month of installation | discrete | numeric | |

BGD_WASH_SWEEP_2018_Water

| | |
|--------------|---|
| Content | This file contains all water point related data collected during this assessment. |
| Cases | 0 |
| Variable(s) | 35 |
| Structure | Type: Keys: () |
| Version | |
| Producer | |
| Missing Data | |

Variables

| ID | NAME | LABEL | TYPE | FORMAT | QUESTION |
|-----|---------------------|---|----------|-----------|----------|
| V50 | id | Facility ID | contin | numeric | |
| V51 | camp | Camp Name | discrete | character | |
| V52 | collection_system | Collection System | discrete | character | |
| V53 | number_taps | Number of taps | discrete | character | |
| V54 | aquifer_type | Aquifer type | discrete | character | |
| V55 | extraction_system | Extraction system | discrete | character | |
| V56 | latrine_disposal | Are there latrines/sludge disposal sites less than 30 feet from the borehole? | discrete | character | |
| V57 | borehole_flood_area | Is the borehole located in a flood prone area? | discrete | character | |
| V58 | borehole_raised | Has the borehole platform been raised to cope with flooding? | discrete | character | |
| V59 | functional | Is it functional? | discrete | character | |
| V60 | issue_no_water | What are the main issues?/no water | discrete | numeric | |
| V61 | issue_no_pump | What are the main issues?/no pump | discrete | numeric | |
| V62 | issue_broken_pump | What are the main issues?/broken pump | discrete | numeric | |
| V63 | issue_other | What are the main issues?/others | discrete | numeric | |
| V64 | condition_hand_pump | Overall condition of the hand pump | discrete | character | |
| V65 | drainage | Is there any proper drainage around the borehole? | discrete | character | |
| V66 | clean_area | cleanliness of the surrounding area | discrete | character | |
| V67 | platform | Is there any platform? | discrete | character | |
| V68 | platform_size | Is the platform size is at least 6 x 7 feet? | discrete | character | |
| V69 | platform_plastered | Is the platform and drainage outlet plastered? | discrete | character | |
| V70 | platform_cracked | Is the platform cracked? | discrete | character | |
| V71 | borehole_use | This borehole is used for: | discrete | character | |
| V72 | bucket_chlorination | Is bucket chlorination currently performed | discrete | character | |
| V73 | dispenser_installed | is there any chlorine dispenser installed? | discrete | character | |
| V74 | water_issues | Is there any specific issues with water quality? | discrete | character | |
| V75 | water_issue_odor | What is the water quality issue?odor | discrete | numeric | |
| V76 | water_issue_taste | What is the water quality issue?taste | discrete | numeric | |

| | | | | |
|-----|-----------------------|---|----------|-----------|
| V77 | water_issue_iron | What is the water quality issue?iron | discrete | numeric |
| V78 | water_issue_saline | What is the water quality issue?saline | discrete | numeric |
| V79 | water_issue_sand | What is the water quality issue?sand | discrete | numeric |
| V80 | water_issue_turbidity | What is the water quality issue?turbidity | discrete | numeric |
| V81 | water_issue_other | What is the water quality issue?other | discrete | numeric |
| V82 | dry_season_borehole | During dry season, what happens to this borehole? | discrete | character |
| V83 | install_year | Year of installation | contin | numeric |
| V84 | install_month | Month of installation | discrete | numeric |

ID (id)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Continuous
 Format: numeric
 Width: 12
 Decimals: 0
 Range: 1-12258

Valid cases: 0
 Invalid: 0

Camp Name (camp)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
 Format: character
 Width: 16

Valid cases: 0
 Invalid: 0

Gender that uses the facility (facility_gender)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
 Format: character
 Width: 13

Valid cases: 0
 Invalid: 0

Number of doors (number_doors)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
 Format: numeric
 Width: 12
 Decimals: 0
 Range: 1-11

Valid cases: 0
 Invalid: 0

Construction Status (construction_status)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
 Format: character
 Width: 9

Valid cases: 0
 Invalid: 0

Number of functional chambers (functional_chamber)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
 Format: numeric
 Width: 12
 Decimals: 0
 Range: 0-10

Valid cases: 0
 Invalid: 0

Number of non functional chambers (non_functional_chamber)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
 Format: numeric
 Width: 12
 Decimals: 0
 Range: 0-10

Valid cases: 0
 Invalid: 0

Is repair needed? (repair_need)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
 Format: character
 Width: 3

Valid cases: 0
 Invalid: 0

Why is the bathing facility non functional? (why_non_functional)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
 Format: character
 Width: 12

Valid cases: 0
 Invalid: 0

Structure type (structure)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
 Format: character
 Width: 56

Valid cases: 0
 Invalid: 0

Does the door close properly? (door_close)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
 Format: character
 Width: 3

Valid cases: 0
 Invalid: 0

Can you see through? (see_through)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

Can you close the door from the inside? (inside_door_close)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

can you close the door from the outside? (outside_door_close)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

For menstrual hygiene management, is a raised platform available?
(mhm_raised_platform)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
Format: numeric
Width: 12
Decimals: 0
Range: 0-1

Valid cases: 0
Invalid: 0

For menstrual hygiene management, is a hanger for drying clothes available? (mhm_hanger)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
Format: numeric
Width: 12
Decimals: 0
Range: 0-1

Valid cases: 0
Invalid: 0

For menstrual hygiene management, is none available? (mhm_none)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
 Format: numeric
 Width: 12
 Decimals: 0
 Range: 0-1

Valid cases: 0
 Invalid: 0

Is there a drain available? (available_drain)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
 Format: character
 Width: 3

Valid cases: 0
 Invalid: 0

Type of drain (drain_type)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
 Format: character
 Width: 32

Valid cases: 0
 Invalid: 0

Year of installation (install_year)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
 Format: numeric
 Width: 10
 Decimals: 0
 Range: 2005-2019

Valid cases: 0
 Invalid: 0

Month of installation (install_month)

File: BGD_WASH_SWEEP_2018_Bathing

Overview

Type: Discrete
 Format: numeric
 Width: 10
 Decimals: 0
 Range: 1-12

Valid cases: 0
 Invalid: 0

Facility ID (id)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Continuous
 Format: numeric
 Width: 12
 Decimals: 0
 Range: 1-11490

Valid cases: 0
 Invalid: 0

Camp Name (camp)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
 Format: character
 Width: 16

Valid cases: 0
 Invalid: 0

Gender that uses the facility (facility_gender)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
 Format: character
 Width: 23

Valid cases: 0
 Invalid: 0

(latrine_type)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
 Format: character
 Width: 26

Valid cases: 0
 Invalid: 0

Number of doors (number_doors)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
 Format: numeric
 Width: 12
 Decimals: 0
 Range: 1-11

Valid cases: 0
 Invalid: 0

Construction Status (construction_status)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
 Format: character
 Width: 9

Valid cases: 0
 Invalid: 0

Number of functional chambers (functional_chamber)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
 Format: numeric
 Width: 12
 Decimals: 0
 Range: 0-10

Valid cases: 0
 Invalid: 0

Is repair needed? (repair_need)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
 Format: character
 Width: 3

Valid cases: 0
 Invalid: 0

Number of non functional chambers (non_functional_chamber)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
 Format: numeric
 Width: 12
 Decimals: 0
 Range: 0-8

Valid cases: 0
 Invalid: 0

Why is the bathing facility non functional? (why_non_functional)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
 Format: character
 Width: 12

Valid cases: 0
 Invalid: 0

(handwash_device)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
 Format: character
 Width: 3

Valid cases: 0
 Invalid: 0

(handwash_device_ok)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

(handwash_device_water)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

(soap)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

(light)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

Structure type (structure)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
Format: character
Width: 56

Valid cases: 0
Invalid: 0

Does the door close properly? (door_close)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

Can you see through? (see_through)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

Can you close the door from the inside? (inside_door_close)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

can you close the door from the outside? (outside_door_close)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

Is a rail (outside) available for pwsn? (pwsn_hand_rail_outside)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
Format: numeric
Width: 12
Decimals: 0
Range: 0-1

Valid cases: 0
Invalid: 0

Is a rail (inside) available for pwsn? (pwsn_hand_rail_inside)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
Format: numeric
Width: 12
Decimals: 0
Range: 0-1

Valid cases: 0
Invalid: 0

Is a ramp available for pwsn? (pwsn_ramp)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
 Format: numeric
 Width: 12
 Decimals: 0
 Range: 0-1

Valid cases: 0
 Invalid: 0

Is a high commode available for pwsn? (pwsn_high_commode)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
 Format: numeric
 Width: 12
 Decimals: 0
 Range: 0-1

Valid cases: 0
 Invalid: 0

Are stairs available for pwsn? (pwsn_stairs)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
 Format: numeric
 Width: 12
 Decimals: 0
 Range: 0-1

Valid cases: 0
 Invalid: 0

Is none available for pwsn? (pwsn_none)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
 Format: numeric
 Width: 12
 Decimals: 0
 Range: 0-1

Valid cases: 0
 Invalid: 0

Year of installation (install_year)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Continuous
 Format: numeric
 Width: 10
 Decimals: 0
 Range: 1995-2019

Valid cases: 0
 Invalid: 0

Month of installation (install_month)

File: BGD_WASH_SWEEP_2018_Latrine

Overview

Type: Discrete
Format: numeric
Width: 10
Decimals: 0
Range: 1-12

Valid cases: 0
Invalid: 0

Facility ID (id)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Continuous
 Format: numeric
 Width: 12
 Decimals: 0
 Range: 1-6767

Valid cases: 0
 Invalid: 0

Camp Name (camp)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
 Format: character
 Width: 16

Valid cases: 0
 Invalid: 0

Collection System (collection_system)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
 Format: character
 Width: 19

Valid cases: 0
 Invalid: 0

Number of taps (number_taps)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
 Format: character
 Width: 7

Valid cases: 0
 Invalid: 0

Acquifer type (aquifer_type)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
 Format: character
 Width: 13

Valid cases: 0
 Invalid: 0

Extraction system (extraction_system)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
 Format: character
 Width: 30

Valid cases: 0
 Invalid: 0

Are there latrines/sludge disposal sites less than 30 feet from the borehole? (latrine_disposal)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

Is the borehole located in a flood prone area? (borehole_flood_area)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

Has the borehole platform been raised to cope with flooding? (borehole_raised)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

Is it functional? (functional)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: character
Width: 7

Valid cases: 0
Invalid: 0

What are the main issues?/no water (issue_no_water)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: numeric
Width: 10
Decimals: 0
Range: 0-1

Valid cases: 0
Invalid: 0

What are the main issues?/no pump (issue_no_pump)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
 Format: numeric
 Width: 10
 Decimals: 0
 Range: 0-1

Valid cases: 0
 Invalid: 0

What are the main issues?/broken pump (issue_broken_pump)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
 Format: numeric
 Width: 10
 Decimals: 0
 Range: 0-1

Valid cases: 0
 Invalid: 0

What are the main issues?/others (issue_other)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
 Format: numeric
 Width: 10
 Decimals: 0
 Range: 0-1

Valid cases: 0
 Invalid: 0

Overall condition of the hand pump (condition_hand_pump)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
 Format: character
 Width: 17

Valid cases: 0
 Invalid: 0

Is there any proper drainage around the borehole? (drainage)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
 Format: character
 Width: 44

Valid cases: 0
 Invalid: 0

cleanliness of the surrounding area (clean_area)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
 Format: character
 Width: 7

Valid cases: 0
 Invalid: 0

Is there any platform? (platform)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

Is the platform size is at least 6 x 7 feet? (platform_size)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

Is the platform and drainage outlet plastered? (platform_plastered)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

Is the platform cracked? (platform_cracked)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

This borehole is used for: (borehole_use)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: character
Width: 31

Valid cases: 0
Invalid: 0

Is bucket chlorination currently performed (bucket_chlorination)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

is there any chlorine dispenser installed? (dispenser_installed)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

Is there any specific issues with water quality? (water_issues)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: character
Width: 3

Valid cases: 0
Invalid: 0

What is the water quality issue?odor (water_issue_odor)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: numeric
Width: 10
Decimals: 0
Range: 0-1

Valid cases: 0
Invalid: 0

What is the water quality issue?taste (water_issue_taste)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: numeric
Width: 10
Decimals: 0
Range: 0-1

Valid cases: 0
Invalid: 0

What is the water quality issue?iron (water_issue_iron)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: numeric
Width: 10
Decimals: 0
Range: 0-1

Valid cases: 0
Invalid: 0

What is the water quality issue?saline (water_issue_saline)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
 Format: numeric
 Width: 10
 Decimals: 0
 Range: 0-1

Valid cases: 0
 Invalid: 0

What is the water quality issue?sand (water_issue_sand)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
 Format: numeric
 Width: 10
 Decimals: 0
 Range: 0-1

Valid cases: 0
 Invalid: 0

What is the water quality issue?turbidity (water_issue_turbidity)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
 Format: numeric
 Width: 10
 Decimals: 0
 Range: 0-1

Valid cases: 0
 Invalid: 0

What is the water quality issue?other (water_issue_other)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
 Format: numeric
 Width: 10
 Decimals: 0
 Range: 0-1

Valid cases: 0
 Invalid: 0

During dry season, what happens to this borehole?

(dry_season_borehole)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
 Format: character
 Width: 60

Valid cases: 0
 Invalid: 0

Year of installation (install_year)

File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Continuous
Format: numeric
Width: 10
Decimals: 0
Range: 1980-2019

Valid cases: 0
Invalid: 0

Month of installation (install_month) File: BGD_WASH_SWEEP_2018_Water

Overview

Type: Discrete
Format: numeric
Width: 10
Decimals: 0
Range: 1-12

Valid cases: 0
Invalid: 0

Documentation

Reports

Bangladesh Wash SWEEP 2018 - Report

Title Bangladesh Wash SWEEP 2018 - Report
Author(s) UNHCR
Country Bangladesh
Language English
Filename <https://microdata.unhcr.org/index.php/catalog/216/download/640>

Technical documents

Bangladesh Wash SWEEP 2018 - Study Documentation

Title Bangladesh Wash SWEEP 2018 - Study Documentation
Author(s) UNHCR
Country Bangladesh
Language English
Filename <https://microdata.unhcr.org/index.php/catalog/216/download/645>
